







| Date    | Person | Reference  | Photo  | Comment   |
|---------|--------|--|--|---|
| 6/1/23  | RB     |                 |  | The fallen tree has been cleared by the Countryside access team   |
| 16/1/23 | RB     | <br>KI113/KI114 |   | It looks like that clearance work has begun on the access from KI113 to KI114. Will ask Countryside Access Team |
| "       | RB     | <br>KI102      |  | Evidence that trees along the part of the path that runs alongside Hendrefoilan school have been cut back       |

|   |    |   |   |   |
|---|----|---|---|---|
| “ | RB |  |  | <p>Tree down in Clyne woods just before the fishing lake which has been reported to Countryside Access Team</p> |
|   |    |   |   |   |
|   |    |   |   |   |
|   |    |   |   |   |
|   |    |   |   |   |